


KITS REVISIONE MONOINIETTORI
SPI repair kits

KIT


TBI Weber 38 mm



R.C.A. 55.000

KIT


TBI Hitachi Subaru



R.C.A. 60.003

KIT


TBI Bosch



R.C.A. 56.000

KIT


TBI Hitachi Nissan



R.C.A. 60.004

KIT


TBI Bosch



R.C.A. 58.000

KIT

TBI Hitachi Nissan



R.C.A. 60.005

KITS REVISIONE MONOINIETTORI




KITS REVISIONE MONOINIETTORI

KITS REVISIONE MONOINIETTORI
SPI repair kits

KIT


TBI Bosch



R.C.A. 60.006

KIT


TBI Weber Ford



R.C.A. 60.008

KIT


TBI 40/44 CIM



R.C.A. 60.009

KIT


TBI 36 MIMO



R.C.A. 60.010

KIT


SPI Bendix-Renix



R.C.A. 60.011

KIT

TBI Bosch



R.C.A. 60.012